



Answers to Spot the Safety Issues

- 1. Dust is creating an inhalation hazard.**
- 2. Low visibility because of the dust. Operator cannot see the worker and the worker cannot see the travel direction of machine.**
- 3. Flying debris could strike the worker.**