

# Farm Equipment Hazards

## Cut Points

0.2 of a second  
=  
10 CUTS



## Pinch Points

0.2 of a second  
=  
Pulled in 14 Ft.



## Wrap Points

0.2 of a second  
=  
Wrapped 2 Ft.



## Free-Wheeling Parts

Some equipment could  
take up to 2.5 min. to  
come to a complete  
stop



## Burn Points

- 124°F takes 3 min.  
for 3<sup>rd</sup> degree burn
- 140°F takes 5 sec.  
for 3<sup>rd</sup> degree burn



## Crush Points

0.2 of a second  
=  
Object Falls 1 Foot  
(based on gravity)



## Stored Energy

Can include hydraulic,  
electrical, chemical, or  
spring tension



## Thrown Objects

Any material or  
object that can  
be thrown by  
equipment



THE OHIO STATE UNIVERSITY  
COLLEGE OF FOOD, AGRICULTURAL,  
AND ENVIRONMENTAL SCIENCES

For more information:  
OSU Agricultural Safety & Health Program  
<http://agsafety.osu.edu>