Grain Handling Safety

Injuries at grain facilities can occur from:

- 1. Suffocation from engulfment
- 2. Respiratory injuries from hazardous gases
- 3. Slips, Trips, Falls on working surfaces
- 4. Entanglement in mechanical equipment
- Electrocution or release of stored energy
- 6. Fire/Explosion from grain dust

If you must enter the bin:

- 1. Shut off and lock out all power.
- 2. Check air quality inside the bin.
- 3. Use a safety harness and safety line.
- 4. Wear proper personal protective equipment.
- 5. Station another person outside the bin to monitor the entry.
- 6. Avoid the center of the bin.